



CPU operation

L: wait until ready is true (**busy waiting**);
 input data from data register to CPU register;
 reset ready to false;
 go to L

Keyboard operation

{Upon pressing a key}
 data register = key value;
 set ready to true